
The First Tool of Lean Manufacturing


Visual Workplace Organization (5S) An orderly, clean, safe, visual arrangement of the workplace that eliminates anything not required, provides a specific location for everything, and eases work.

The visual system makes "Abnormalities Leap to the Eye" for all. Everything is "Easy to See. Easy to Get. Easy to Return.



The First Tool of Lean Manufacturing Visual Workplace Organization (5S) An orderly, clean, safe, visual arrangement of the workplace that eliminates anything not required, provides a specific location for everything, and eases work.

The visual system makes "Abnormalities Leap to the Eye" for all. Everything is "Easy to See. Easy to Get. Easy to Return.



SIFT: Needed / Not Needed

- Determine what is needed/not needed. Remove all items from the workplace that are not needed.
- Determine Max/Min amounts.
- Establish a Red Tag Area and create Basic Rules.

SORT: Visualize Home Position

- *Easy to See, Easy to Get, Easy to Return.*Create total visual standard by sorting & labeling.
- Frequent items closer. All items for one job together.
- MAPS: Area Layout Map for the area under 5S control.
 MAPS: Sub-Area Maps (if needed)
- MAPS: Sub-Area Maps (if needed)

SWEEP & WASH: Cleaning Is Inspection!

- Clean everything on a schedule and as-needed.
 Use your senses (Look, Listen, Smell, & Touch) in a safe manner to detect abnormalities.
- MAPS: Zone Maps.
- MAPS: 5S Activity Cards/Schedule.

SPIC & SPAN: Total Standardization

- Abnormalities "Leap to the Eye."
- Make photos of Home Position down to the lowest level.
 Develop standards for every photo/item->Home Position
- Create "Unbreakable" conditions.
- MAPS: Photo Maps and Standards

SUSTAIN: Achieve Workplace Safety & Productivity

Establish formal roles for sustaining the full 5S condition
Establish/conduct regular 5S audits and follow-up plans.

SIFT: Needed / Not Needed

- Determine what is needed/not needed. Remove all items from the workplace that are not needed.
- Determine Max/Min amounts.
- Establish a Red Tag Area and create Basic Rules.

SORT: Visualize Home Position

- Easy to See, Easy to Get, Easy to Return.
- Create total visual standard by sorting & labeling.Frequent items closer. All items for one job together.
- MAPS: Area Layout Map for the area under 5S control.
- MAPS: Sub-Area Maps (if needed)

SWEEP & WASH: Cleaning Is Inspection!

Clean everything on a schedule and as-needed.
Use your senses (Look, Listen, Smell, & Touch) in a safe manner to detect abnormalities.

- MAPS: Zone Maps.MAPS: 5S Activity Cards/Schedule.
- Infil 5. 55 Heavily Calas benediate.

SPIC & SPAN: Total Standardization

- Abnormalities "Leap to the Eye."
- Make photos of Home Position down to the lowest level.
 Develop standards for every photo/item->Home Position
- Develop standards for every photo/ne
 Create "Unbreakable" conditions.
- MAPS: Photo Maps and Standards
- ×.

SUSTAIN: Achieve Workplace Safety & Productivity • Establish formal roles for sustaining the full 5S conditio

Establish/conduct regular 5S audits and follow-up plans.

The First Tool of Lean Manufacturing Visual Workplace Organization (55)

Visual Workplace Organization (5S) An orderly, clean, safe, visual arrangement of the workplace that eliminates anything not required, provides a specific location for everything, and eases work.


The visual system makes "Abnormalities Leap to the Eye" for all. Everything is "Easy to See. Easy to Get. Easy to Return.



The First Tool of Lean Manufacturing

Visual Workplace Organization (5S) An orderly, clean, safe, visual arrangement of the workplace that eliminates anything not required, provides a specific location for everything, and eases work.

The visual system makes "Abnormalities Leap to the Eye" for all. Everything is "Easy to See. Easy to Get. Easy to Return.



SIFT: Needed / Not Needed

- Determine what is needed/not needed. Remove all items from the workplace that are not needed.
- Determine Max/Min amounts.
- Establish a Red Tag Area and create Basic Rules.

SORT: Visualize Home Position

- Easy to See, Easy to Get, Easy to Return.
- Create total visual standard by sorting & labeling.Frequent items closer. All items for one job together.
- MAPS: Area Layout Map for the area under 5S control.
- MAPS: Sub-Area Maps (if needed)

-

- SWEEP & WASH: Cleaning Is Inspection!
- Clean everything on a schedule and as-needed.
- Use your senses (Look, Listen, Smell, & Touch) in a safe manner to detect abnormalities.
 - abnormalities.
- MAPS: Zone Maps.MAPS: 5S Activity Cards/Schedule.

SPIC & SPAN: Total Standardization

• Abnormalities "Leap to the Eye."

- Make photos of Home Position down to the lowest level.
- Develop standards for every photo/item->Home Position
- Create "Unbreakable" conditions.
- MAPS: Photo Maps and Standards

SUSTAIN: Achieve Workplace Safety & Productivity

Establish formal roles for sustaining the full 5S condition.
Establish/conduct regular 5S audits and follow-up plans.

Establish/conduct regular 55 audits and follow-up plans.

SIFT: Needed / Not Needed

- Determine what is needed/not needed. Remove all items from the workplace that are not needed.
- Determine Max/Min amounts.
- Establish a Red Tag Area and create Basic Rules.

SORT: Visualize Home Position

- Easy to See, Easy to Get, Easy to Return.
- Create total visual standard by sorting & labeling.
- Frequent items closer. All items for one job together.
- MAPS: Area Layout Map for the area under 5S control.
 MAPS: Sub-Area Maps (if needed)

SWEEP & WASH: Cleaning Is Inspection!

Clean everything on a schedule and as-needed.
Use your senses (Look, Listen, Smell, & Touch) in a safe

manner to detect abnormalities.

• MAPS: Zone Maps.

MAPS: 5S Activity Cards/Schedule.

SPIC & SPAN: Total Standardization

- Abnormalities "Leap to the Eye."
- Make photos of Home Position down to the lowest level.
- Develop standards for every photo/item->Home Position
- Create "Unbreakable" conditions.
 MAPS: Photo Maps and Standards


SUSTAIN: Achieve Workplace Safety & Productivity

• Establish formal roles for sustaining the full 5S condition

• Establish/conduct regular 5S audits and follow-up plans.


The First Tool of Lean Manufacturing Visual Workplace Organization (5S) An orderly, clean, safe, visual arrangement of the workplace that eliminates anything not required, provides a specific location for everything, and eases work.

The visual system makes "*Abnormalities Leap to the Eye*" *for all.* Everything is "*Easy to See. Easy to Get. Easy to Return.*



The First Tool of Lean Manufacturing Visual Workplace Organization (5S) An orderly, clean, safe, visual arrangement of the workplace that eliminates anything not required, provides a specific location for everything, and eases work.

The visual system makes "Abnormalities Leap to the Eye" for all. Everything is "Easy to See. Easy to Get. Easy to Return.



SIFT: Needed / Not Needed

- Determine what is needed/not needed. Remove all items from the workplace that are not needed.
- Determine Max/Min amounts.
- Establish a Red Tag Area and create Basic Rules.

SORT: Visualize Home Position

• Easy to See, Easy to Get, Easy to Return. • Create total visual standard by sorting & labeling. • Frequent items closer. All items for one job together. • MAPS: Area Layout Map for the area under 5S control. • MAPS: Sub-Area Maps (if needed)

SWEEP & WASH: Cleaning Is Inspection!

• Clean everything on a schedule and as-needed. • Use your senses (Look, Listen, Smell, & Touch) in a safe manner to detect abnormalities. • MAPS: Zone Maps. • MAPS: 5S Activity Cards/Schedule.

SPIC & SPAN: Total Standardization

- Abnormalities "Leap to the Eye." • Make photos of Home Position down to the lowest level
- Develop standards for every photo/item->Home Position
- Create "Unbreakable" conditions.
- MAPS: Photo Maps and Standards

SUSTAIN: Achieve Workplace Safety & Productivity

• Establish formal roles for sustaining the full 5S condition • Establish/conduct regular 5S audits and follow-up plans.

SIFT: Needed / Not Needed

- Determine what is needed/not needed. Remove all items from the workplace that are not needed.
- Determine Max/Min amounts.
- Establish a Red Tag Area and create Basic Rules.

SORT: Visualize Home Position

- Easy to See, Easy to Get, Easy to Return.
- Create total visual standard by sorting & labeling.
- Frequent items closer. All items for one job together. • MAPS: Area Layout Map for the area under 5S control.
- MAPS: Sub-Area Maps (if needed)

SWEEP & WASH: Cleaning Is Inspection!

• Clean everything on a schedule and as-needed. • Use your senses (Look, Listen, Smell, & Touch) in a safe manner to detect abnormalities. • MAPS: Zone Maps. • MAPS: 5S Activity Cards/Schedule.

SPIC & SPAN: Total Standardization


- Abnormalities "Leap to the Eve." • Make photos of Home Position down to the lowest level.
- Develop standards for every photo/item->Home Position
- Create "Unbreakable" conditions.
- MAPS: Photo Maps and Standards

SUSTAIN: Achieve Workplace Safety & Productivity Establish formal roles for sustaining the full 5S condition • Establish/conduct regular 5S audits and follow-up plans.

The First Tool of Lean Manufacturing

Visual Workplace Organization (5S) An orderly, clean, safe, visual arrangement of the workplace that eliminates anything not required, provides a specific location for everything, and eases work.


The visual system makes "Abnormalities *Leap to the Eye''* for all. Everything is "Easy to See. Easy to Get. Easy to Return.



The First Tool of Lean Manufacturing Visual Workplace Organization (5S)

An orderly, clean, safe, visual arrangement of the workplace that eliminates anything not required, provides a specific location for everything, and eases work.

The visual system makes "Abnormalities *Leap to the Eye'' for all.* Everything is "Easy to See. Easy to Get. Easy to Return.



SIFT: Needed / Not Needed

- Determine what is needed/not needed. Remove all items
- from the workplace that are not needed.
- Determine Max/Min amounts.
- Establish a Red Tag Area and create Basic Rules.

ORT: Visualize Home Position

- Easy to See, Easy to Get, Easy to Return.
- Create total visual standard by sorting & labeling.
- Frequent items closer. All items for one job together.
- MAPS: Area Layout Map for the area under 5S control.
- MAPS: Sub-Area Maps (if needed)

SWEEP & WASH: Cleaning Is Inspection!

- Clean everything on a schedule and as-needed.
- Use your senses (Look, Listen, Smell, & Touch) in a safe
- manner to detect abnormalities.
- MAPS: Zone Maps.
- MAPS: 5S Activity Cards/Schedule.

SPIC & SPAN: Total Standardization

- Abnormalities "Leap to the Eye."
- Make photos of Home Position down to the lowest level.
- Develop standards for every photo/item->Home Position
- Create "Unbreakable" conditions.
- MAPS: Photo Maps and Standards

USTAIN: Achieve Workplace Safety & Productivity · Establish formal roles for sustaining the full 5S condition

• Establish/conduct regular 5S audits and follow-up plans.

SIFT: Needed / Not Needed

- Determine what is needed/not needed. Remove all items
- from the workplace that are not needed.
- Determine Max/Min amounts.
- Establish a Red Tag Area and create Basic Rules.

ORT: Visualize Home Position

- Easy to See, Easy to Get, Easy to Return.
- Create total visual standard by sorting & labeling.
- Frequent items closer. All items for one job together.
- MAPS: Area Layout Map for the area under 5S control.
- MAPS: Sub-Area Maps (if needed)


WEEP & WASH: Cleaning Is Inspection!

- Clean everything on a schedule and as-needed.
- Use your senses (Look, Listen, Smell, & Touch) in a safe
- manner to detect abnormalities.
- MAPS: Zone Maps.
- MAPS: 5S Activity Cards/Schedule.

SPIC & SPAN: Total Standardization

- Abnormalities "Leap to the Eve."
- Make photos of Home Position down to the lowest level.
- Develop standards for every photo/item->Home Position
- Create "Unbreakable" conditions.
- MAPS: Photo Maps and Standards


USTAIN: Achieve Workplace Safety & Productivity · Establish formal roles for sustaining the full 5S condition Establish/conduct regular 5S audits and follow-up plans.



Visual Workplace Organization (5S) An orderly, clean, safe, visual arrangement of the workplace that eliminates anything not

required, provides a specific location for everything, and eases work.

The visual system makes "Abnormalities *Leap to the Eye'' for all.* Everything is 'Easy to See. Easy to Get. Easy to Return.



The First Tool of Lean Manufacturing

Visual Workplace Organization (5S) An orderly, clean, safe, visual arrangement of the workplace that eliminates anything not required, provides a specific location for everything, and eases work.

The visual system makes "Abnormalities *Leap to the Eye''* for all. Everything is 'Easy to See. Easy to Get. Easy to Return.

The First Tool of Lean Manufacturing

SIFT: Needed / Not Needed

- Determine what is needed/not needed. Remove all items from the workplace that are not needed.
- Determine Max/Min amounts.
- Establish a Red Tag Area and create Basic Rules.

SORT: Visualize Home Position

- Easy to See, Easy to Get, Easy to Return.
- Create total visual standard by sorting & labeling.
- Frequent items closer. All items for one job together.
- MAPS: Area Layout Map for the area under 5S control.
- MAPS: Sub-Area Maps (if needed)

SWEEP & WASH: Cleaning Is Inspection!

• Clean everything on a schedule and as-needed. • Use your senses (Look, Listen, Smell, & Touch) in a safe

- manner to detect abnormalities.
- MAPS: Zone Maps.
- MAPS: 5S Activity Cards/Schedule.

SPIC & SPAN: Total Standardization

- Abnormalities "Leap to the Eye."
- Make photos of Home Position down to the lowest level.
- Develop standards for every photo/item->Home Position
- Create "Unbreakable" conditions.
- MAPS: Photo Maps and Standards

SUSTAIN: Achieve Workplace Safety & Productivity

• Establish formal roles for sustaining the full 5S condition • Establish/conduct regular 5S audits and follow-up plans.

SIFT: Needed / Not Needed

- Determine what is needed/not needed. Remove all items from the workplace that are not needed.
- Determine Max/Min amounts.
- Establish a Red Tag Area and create Basic Rules.

SORT: Visualize Home Position

- Easy to See, Easy to Get, Easy to Return.
- Create total visual standard by sorting & labeling.
- Frequent items closer. All items for one job together.
- MAPS: Area Layout Map for the area under 5S control.
- MAPS: Sub-Area Maps (if needed)

SWEEP & WASH: Cleaning Is Inspection!

• Clean everything on a schedule and as-needed.

• Use your senses (Look, Listen, Smell, & Touch) in a safe manner to detect abnormalities.

- MAPS: Zone Maps.
- MAPS: 5S Activity Cards/Schedule.

SPIC & SPAN: Total Standardization

- Abnormalities "Leap to the Eve."
- Make photos of Home Position down to the lowest level.
- Develop standards for every photo/item->Home Position
- Create "Unbreakable" conditions.
- MAPS: Photo Maps and Standards

SUSTAIN: Achieve Workplace Safety & Productivity

- Establish formal roles for sustaining the full 5S condition
- Establish/conduct regular 5S audits and follow-up plans.